

# 2GO H02

## Bluetooth Headset

### User Manual


Bluetooth headset should be used with the compatible devices which support bluetooth wireless technology. This allows you the freedom to make any calls at any time. Please read this user manual carefully before using the headset, and also read your device's user manual regarding the bluetooth function, and pay attention to those important safety and maintenance information. Please keep the headset away from children.

#### Specifications

<b>Bluetooth Specification</b>	V3.0
<b>Bluetooth Profiles</b>	Headset, Handsfree
<b>Supported</b>	Class 2
<b>Transmission Power</b>	Up to 10 Meters
<b>Operation Range</b>	2.400~2.4835 GHz
<b>Frequency Range</b>	Built-in Rechargeable
<b>Battery</b>	3.7V Li-polymer Battery
<b>Charging Voltage</b>	DC4.75-5.25V
<b>Charging Time</b>	About 2 hours
<b>Talk Time*</b>	Up to 4 hours
<b>Standby Time*</b>	Up to 100 hours
<b>Dimensions(mm)</b>	L33 X W16 X H9.5
<b>Weight</b>	About 6.3g

\*May vary due to user's operation mode and device settings.

#### Structure Sketch



- (1) Indicator Light
- (2) Multifunction Button(MFB)
- (3) Charging Socket

- (4) Ear Hook
- (5) Microphone
- (6) Speaker

#### Basic Operations

##### Charging Your Headset

Prior to using the headset for the first time, please fully charge the battery.

Approximately 2 hours are required to fully charge the headset.

The indicator light turns red while being charged, and will turn blue automatically after being fully charged.

When the headset is running out of battery, it beeps and the indicator light will flash red(the headset will switch off automatically when the battery is drained). Please charge the headset as above steps in time to prolong the battery's useful life (Charging indication will be delayed for a few minutes if the headset has not been used for a long time or the battery is drained).

##### Note:

Use only the supplied charger to charge the headset, or could be dangerous.

Do not attempt to force open the built-in battery as this could damage the headset.

If left unused, a fully charged headset will lose its power automatically. It is recommended to charge the headset every three months.

Do not leave the headset in a too hot or too cold condition (best between 15°C and 25°C ) which may affect the headset's operations.

Do not dispose of the headset into a fire and water.

##### Turning on the Headset

In OFF MODE, press and hold MFB until the indicator light flashes blue, then the headset will enter into STANDBY MODE.

##### Turning off the Headset

In ON MODE, press and hold MFB until the indicator light flashes red, then the headset will enter into OFF MODE.

##### Pairing Your Headset with a Bluetooth Mobile Phone

- 1.Ensure the headset is off, and the distance between your headset and phone is within 1 meter.
- 2.Press and hold MFB until the indicator light flashes blue and red alternately as PAIRING MODE.
- 3.Activate the bluetooth function on the phone, search bluetooth devices (See the user guide of your phone for instructions).
- 4.Select headset "2GO H02" from the found devices list of the phone.
- 5.Enter the passkey "0000". confirm to pair the headset with your phone.(If the pairing cannot be completed within 5 minutes after the PAIRING MODE has been activated, the headset will enter into the STANDBY MODE. Repeat above steps to do the pairing again).
- 6.Ensure the distance between your headset and phone is within 10 meters, and without any obstacles. You can use the headset freely.
- 7.If the headset had paired with your phone but disconnected, it will paired automatically again when turns on within operation range.

##### Answering/Ending a Call

Press MFB once

##### Rejecting a Call

Press and hold MFB

##### Voice Dialing

In STANDBY MODE, press MFB once and say the voice tag as soon as you hear the short beep(ensure your phone supports voice dialing function, and you have recorded the voice tag into your phone. See the user guide of your phone for instructions.)

##### Last Number Redialing

Press and hold MFB for 3 seconds

##### Power Save

The headset will turn off automatically if it can not be paired or disconnected with any devices within 20 minutes.

##### Disconnecting

To disconnect the paired headset from your phone, please turn off the headset or disconnect the headset from the Bluetooth menu of your phone.

##### Care and Maintenance

Do not use abrasive cleaning solvents to clean the headset.

Do not allow the headset to come into contact with sharp objects as this will cause scratching and damage.

Be sure to store the headset in a dry place, free from extreme temperatures, humidity and dust.

##### Additional Statements

The Headset is compliant with the specified Bluetooth version. It does not guarantee compatibility of all functions on every Bluetooth enabled device. Please check your device's user manual for compatibility and functionality. Charge the headset under any status to a reset.

The headset will turn off automatically if it can not be paired with any devices within 20 minutes.

The headset will beep when operates successfully and this maybe too low to hear.

The above operations may vary due to different devices.

Manufacturer reserves the right of final explanation of all the above statements.